

Recovery project name	Basic description of damage	Project Status
Bain - Tumby Left Bank breach & Right Bank erosion Tumby	Embankment breach. This asset breached during high flows from Storm Babet. This has left a 35 metre breach in the embankment and approx 200m erosion upstream.	Not funded
Bain Left Bank - Tattershall breach Tattershall	Embankment breach. This asset breached during high flows from Storm Babet.	Construction
Bain u/s Shearman's Wath Bridge Right Bank erosion u/s Shearman's Wath Bridge	Erosion causing crest damage due to overtopping.	Not Funded
Barlings Eau Left Bank breach Short Ferry, Stainfield Fen	Embankment breach.	Complete
Barlings Eau Left Bank slip Short Ferry, Stainfield Fen	Crest has visible bare patches and major slippage slowly creeping into it.	Not Funded
Barlings Eau Right Bank breach d/s Barlings Abbey	Embankment breach. This asset breached during high flows from Storm Babet.	Complete
Barlings Eau Right Bank erosion	Damage from Storm Babet & Storm Henk to the landward face from the wave action from the flood cell due to breach upstream.	Not Funded
Boultham Catchwater Drain breach	Repaired by developer on site. No plans to undertake any further work.	Not Required

If you have any queries please contact
Inenquiries@environment-agency.gov.uk

Project Status Explainer

Not Funded: we do not currently have the funding to carry out the repair. We will keep this under review, and should the situation with risk or funding change, we may be able to carry out a repair.

Design: we have the funding for the repair and we are working with our contractors on the design. We will share a further detail and a start date when they are available.

Construction: the repair is in progress.

Investigation: specialist will be commissioned to review the scale of impact and recommend any additional works required.

Complete: the repair is complete.

Not required: we have assessed the damage and a repair is not required. This may be the result of a third party undertaking their own repair.

Bourne Eau Right Bankbreach d/s Bourne	Embankment breach.	Complete
Bourne Eau Right Bank slips d/s Bourne	Embankment slips.	Design
Branston Delph Left Bank erosion	Following Storm Henk Branston Delph filled and overtopped. There is scour damage on the landward face from overtopping.	Design
Burton Catchwater Left Bank breach Lincoln	Embankment breach. This asset breached during high flows from Storm Babet. Site user has undertaken a temporary repair.	Design
Criquet Till Left Bank slip u/s Tillbridge Lane	Slip on the landward face.	Design
Farroway Drain Right Bankscour erosion	Embankment breach. Landward face scour/erosion due to flow through animal burrows causing wash out and reduction in embankment cross section.	Design
Glen Right Bank erosion	Erosion/slips on exposed face.	Not Funded
Great Gowts Drain Right Bank wall seepage Sewell's Walk, Lincoln	The floodwall was seeping during Storm Babet, with high flows resulting in the floodwall being undermined and washing out the material underneath.	Not Funded
Ruskington Outstation Replacement	Outstation failed due to being drowned out during Storm Babet.	Not Funded
Sandhill Beck Outstation Replacement	Outstation failed due to being drowned out during Storm Babet.	Not Funded

Helpringham Eau Left Bank slip Millfield Farm, Screddington	15m long slip along edge of crest.	Not Funded
Marsh Drain Left Bank breach confluence with Stainfield Beck to Sambre Beck	Embankment breach. This asset was damaged during Storm Babet, leaving a breach at Marsh Drain, along with the extensive damage to the left bank from landward face slip.	Design
Maxey Cut Left Bank erosion	Bank damage from Storm Henk along two sections of this asset. Emergency repairs completed. Funding secured for a permanent repair.	Design
Middle Ancholme Right Bank erosion	Overtopping during Storm Henk, location at upstream end of asset resulting in scour damage to landward face.	Not Funded
North Kelsey Beck Left Bank breach North Kelsey	Embankment breach. This asset breached during high flows from Storm Babet. Landowner has undertaken a temporary repair.	Design
S40ft Left Bank erosion	Overtopping caused erosion to the landward face in various sections.	Design
S40ft Right Bank erosion	Damage to the landward face of the embankment due to overtopping.	Design
Sincil Dyke Right Bank floodwall seepage Lincoln, Football Ground	Seepage through and underneath the wall when the river levels were high during Storm Babet and Storm Henk.	Not Funded
South Delph Right Bank (u/s Sandhill Beck) scour	Damage from overtopping on the landward face during Storm Babet & Storm Henk.	Design
South Delph Right Bank crack and seepage Branston Fen	Large crack and seepage.	Design

Stainfield Beck Left Bank slips Stainfield Fen	Assets were damaged during overtopping during Storm Babet, leaving multiple slips along the assets and erosion.	Not Funded
Steeping Right Bank bank damage	Storm Babet damage to the landward face of the asset at a couple of locations. This was as a result of prolonged overtopping of the asset.	Design
Tetney Mother Drain Left Bank erosion u/s Thoresby Road Bridge	Hole in exposed face.	Not Funded
Tetney Mother Drain Right Bank erosion	Post Storm Babet inspection determined there was a slip on the exposed face.	Not Funded
Tidal Welland Left Bank slip	Bank slip during Storm Henk on tidal Welland reported by IDB.	Design
Till Right Bank erosion and settlement u/s Squires Bridge	Erosion and settlement.	Design
Timberland Delph Right Bank scour erosion	Landward face scour/erosion due to overtopping causing reduction in embankment cross section.	Design
Waterways Lower Wellingborough fencing repairs	Lower Wellingborough canoe portage fencing damage.	Not Funded
Welland Cradge Bank breach (Crowland & Cowbit Washland) Breach 1	Embankment breach.	Design
Welland Cradge Bank breach (Crowland & Cowbit Washland) Breach 2	Embankment breach	Design

West Fen Catachwater Right Bank slips & erosion 1 Hagnaby Lock	Small but widespread slips and erosion on exposed face.	Design
West Fen Catchwater Right Bank erosion 2	This asset was damaged during high flows from Storm Babet.	Design
Winterton Beck Left Bank breach Winteringham	Embankment breach during high flows from Storm Babet.	Design
Witham in Lincoln Left Bank floodwall seepage	Reports of seepage through flood wall.	Investigation
Witham Left Bank Fiskerton slips Fiskerton	Two c.20m slips on the landward face due to high levels along the River Witham from Storm Babet.	Design